


Spider-80SG: Breakout Box Terminal Guide

Application Note 036



Trung-Duong Nguyen - Application Engineer

April 2018 | © Crystal Instruments Corporation

Contents

A. Introduction.....	3
B. Hardware Connection.....	3
C. Input Channel Table Setup.....	5

A. Introduction

One of the most common inquiries we receive is regarding strain gage setup on the Spider-80SG. The Spider-80SG is designed to be used with strain gages, with the added advantage of utilizing the same intuitive interface from our EDM software platform. The connection to Spider-80SG breakout box is the final piece of the puzzle and it is a lot simpler than it looks.

The idea of having the breakout box is to provide users with flexibility to have multiple configuration types available to users. Depending on the application, users are free to choose whichever configuration suitable to their needs. We will explain a few primary configurations in this paper. To measure strain value, the resistance to be measured must be configured by a complete full-bridge circuit. By using the super-position technique, users will have the ability to complete a full-bridge circuit and select part of the equation to take measurement.

B. Hardware Connection

The breakout box is primarily comprised of the following pins: (Table 1 and Figure 1.1)

Positive and Negative Excitation sensing are used when the strain gage is located at a certain distance from the Spider, which results in a significant drop of the Excitation voltage that is fed to the Strain gage. In this case, a precise value of the excitation voltage is needed to measure strain accurately.

EXE + from the bridge needs to be connected to **SEN +** and **EXE -** from the bridge needs to be connected to the **SEN -** to measure the excitation voltage at the bridge.

Name	Description
EXC+	Positive Excitation (+2.5V/ +5V)
EXC-	Negative Excitation (-2.5V/-5V)
SEN+	Positive excitation sensing
SEN-	Negative excitation sensing
IN+	Positive input
IN-	Negative input
350	350 Ω terminal
120	120 Ω terminal
GND	Ground

Table 1



Figure 1.1




Figure 1.2

Strain gages usually include a 2 or 3-wire terminal. The 3-wire configuration consists of one cable attached to one terminal, and 2 remaining cables are attached to the second terminal. Strain Gages can be connected in the following five basic types of configurations:

(For simplicity, we recommend configuration 1 and 2)

- 1. QUARTER BRIDGE TYPE I, 2-WIRE CONFIGURATION:** In this configuration, there is only one Strain Gage connected to measure the strain from the test object.

(Figure 1.2)

The strain gage is connected between the EXC+ and IN- terminals as shown. The two terminals of the Strain Gage are interchangeable for this configuration.

Resistors R_{W1} and R_{W2} denote the wire resistances of the two wires originating from the strain gage and are connected to the Spider-80SG terminals.

Breakout Box Connections: (Table 2)

Strain Gage Terminals	Spider-80SG Break Out Box
Strain Gage Terminal 1	EXC+
Strain Gage Terminal 2	IN-

Table 2




Figure 1.3

2. QUARTER BRIDGE TYPE I, 3-WIRE CONFIGURATION:

Most Strain Gages have 3 wires (2 wires originating from one of the terminals and 1 wire from the other terminal), this is usually done to compensate for the resistance added by the wire.

One disadvantage of the Quarter Bridge Type I (2-Wire Configuration) is that the resistances caused by the lead wires from the terminals of the strain gage add a small additional value of resistance to the arm of the bridge to which it is connected to. For example, if a 120Ω strain gage is connected, the actual resistance would be $120 + R_{W1} + R_{W2} \Omega$. The other internal resistor in the arm would be 120Ω , resulting in a slightly off-balance bridge. Since the strain gage works with very minute changes in the resistances, the value of $R_{W1} + R_{W2}$, although small, can affect readings.

With the 3-wire configuration, as shown below, the third wire is connected in such a way that the wire resistance is added to both resistors of the arm. (Figure 1.3)

The third wire needs to be connected to a pin marked either 120Ω or 350Ω on the breakout box depending on the resistance of the connected strain gage

Strain Gage Terminals	Spider-80SG Break Out Box
Strain Gage Terminal 1	EXC+
Strain Gage Terminal 2	IN-
Strain Gage Terminal 2	$120 \Omega / 350 \Omega$

Table 3

Strain Gage Terminals	Spider-80SG Break Out Box
Strain Gage 1 Terminal 1	EXC+
Strain Gage 1 Terminal 2	IN-
Strain Gage 2 Terminal 1 (Dummy / Passive)	IN-
Strain Gage 2 Terminal 2 (Dummy / Passive)	EXC-

Table 4

It should be ensured that the terminal of the strain gage with 2 wires needs to be connected to IN- and $120/350\Omega$. The other terminal of Strain gage with one wire should be connected to EXC+.

With the above configuration, assuming 120Ω strain gage is connected.

Resistance between EXC+ and IN- = $120 \Omega + R_{W1} + R_{W2}$

Resistance between IN- and EXC - = 120Ω (Internal) + $R_{W2} + R_{W3}$

The resistances R_{W1} , R_{W2} , R_{W3} primarily depend on their length (as

they are made of same material and operated at the same temperature), so when the length is ensured to be about the same, then $R_{W1} = R_{W2} = R_{W3}$ making the above bridge, with 3-wire configuration, balanced. (Table 3)

3. QUARTER BRIDGE TYPE

II: Quarter Bridge Type II is typically used for temperature compensation. Due to the changes in the temperature, the resistance of the strain gage will not be constant making the bridge out of balance even when there is no external strain applied.

To compensate for the changes in temperature, a second dummy strain

gauge is attached between IN- and EXC- similar to a Half Bridge configuration. However, the dummy strain gauge does not measure strain of any kind and should not be connected to the object undergoing stress. As the dummy strain gauge is placed in the same environment as the strain gauge measuring strain, both strain gauges are subject to the same temperature. Any change in the temperature would influence change the resistances of both strain gauges equally and hence making the bridge balanced. (Table 4)

Each strain gauge connected also has R_{w1} and R_{w2} associated with it making the bridge balanced.

4. **HALF BRIDGE:** For both Half Bridge Type I and Type II configurations, there are two active strain gauges completing one arm of the bridge. (Table 5)

The other arm of the bridge is internal. Since, both strain gauges are operated in the same environment with similar wire lengths, the bridge is balanced by default.

5. **FULL BRIDGE:** For both Full Bridge Type I and Type II configurations, all 4 resistors (strain gauges) of the bridge are external. (Table 6)

C. Input Channel Table Setup

Test Configuration is similar to our standard DSA test setup. There are only a few items to look in Input Channels setup for the strain gauge on Spider-80SG.

To set the input channel table, navigate to menu item **Setup > Input channels**. (Figure 2.1)

Set the required Measurement Quantity for Spider 80X channels and the Spider 80SG channels. For non-strain channels, set the Sensitivity and

Strain Gauge Terminals	Spider-80SG Break Out Box
Strain Gauge 1 Terminal 1	EXC+
Strain Gauge 1 Terminal 2	IN-
Strain Gauge 2 Terminal 1	IN-
Strain Gauge 2 Terminal 2	EXC-

Table 5

Strain Gauge Terminals	Spider-80SG Break Out Box
Strain Gauge 1 Terminal 1	EXC+
Strain Gauge 1 Terminal 2	IN-
Strain Gauge 2 Terminal 1	IN-
Strain Gauge 2 Terminal 2	EXC-
Strain Gauge 3 Terminal 1	EXC-
Strain Gauge 3 Terminal 2	IN+
Strain Gauge 4 Terminal 1	IN+
Strain Gauge 4 Terminal 2	EXC+

Table 6

Fill	Ex/Im	Units	Sensor	Load from library	Save to library	Save as default		
On/Off	Location ID	Measurement quantity	Sensitivity	Input mode	Sensor	Input range	High-Pass filter Fc (Hz)	Power supply
<input checked="" type="checkbox"/>	Ch1	Acceleration	100.0000 (mV/g)	IEPE		Auto	2.0000	
<input checked="" type="checkbox"/>	Ch2	Acceleration	100.0000 (mV/g)	IEPE		Auto	2.0000	
<input checked="" type="checkbox"/>	Ch3	Acceleration	100.0000 (mV/g)	IEPE		Auto	2.0000	
<input checked="" type="checkbox"/>	Ch4	Acceleration	100.0000 (mV/g)	IEPE		Auto	2.0000	
<input checked="" type="checkbox"/>	Ch5	Sound Pressure	50.0000 (mV/Pa)	IEPE		Auto	2.0000	
<input type="checkbox"/>	Ch6	Acceleration	100.0000 (mV/g)	DC-Single End		Auto	2.0000	
<input type="checkbox"/>	Ch7	Acceleration	100.0000 (mV/g)	DC-Single End		Auto	2.0000	
<input type="checkbox"/>	Ch8	Acceleration	100.0000 (mV/g)	DC-Single End		Auto	2.0000	
<input checked="" type="checkbox"/>	Ch9	Strain	N/A	DC-Differential		10mV	Off	Unusable(2...
<input type="checkbox"/>	Ch10	Acceleration	100.0000 (mV/g)	AC-Differential		10mV	Off	Unusable(2...

Figure 2.1

Bridge type	Three lines	Gage factor	Nominal gage resistance (Ω)	Excitation voltage	Remote sensing	Calibration
Quarter I	<input type="checkbox"/> Off	2.13	120	2.5V	<input type="checkbox"/> Off	<input checked="" type="checkbox"/> On
Quarter I	<input type="checkbox"/> Off	2.13	120	2.5V	<input type="checkbox"/> Off	<input checked="" type="checkbox"/> On
Quarter I	<input type="checkbox"/> Off	2.13	120	2.5V	<input type="checkbox"/> Off	<input checked="" type="checkbox"/> On
Quarter I	<input type="checkbox"/> Off	2.13	120	2.5V	<input type="checkbox"/> Off	<input checked="" type="checkbox"/> On
Full I	N/A	2.08	120	2.5V	<input type="checkbox"/> Off	<input checked="" type="checkbox"/> On
Full I	N/A	2.08	120	2.5V	<input type="checkbox"/> Off	<input checked="" type="checkbox"/> On
Full I	N/A	2.08	120	2.5V	<input type="checkbox"/> Off	<input checked="" type="checkbox"/> On

Figure 2.2

the Input mode. For Strain channels, set the Input range and then click on the tab **Strain Gauge parameters** for further strain gauge related settings.

Strain gauge parameters are unique and are very different from your normal accelerometers. (Figure 2.2)

For the enabled channels, select **Bridge type** (depends on your configuration), **Nominal gage resistance** and the **Excitation voltage**. It is recommended to enable the Calibration at all times (Input channel must be calibrated before

taking any measurements).

Enter the value of Gage factor depending on the type of strain gage being used.

Click on **OK** to complete the setup, and we are ready to take our measurements. Just be sure to calibrate and re-zero the strain gage before every measurement as standard practice for best data.

Crystal Instruments Corporation
2090 Duane Avenue
Santa Clara, CA 95054

Crystal Instruments Testing Lab
15661 Producer Lane, STE H
Huntington Beach, CA 92649

Crystal Instruments Testing Lab
1548A Roger Dale Carter Boulevard
Kannapolis, NC 28081

Phone: +1 (408) 986-8880
Fax: +1 (408) 834-7818
www.crystalinstruments.com

© 2023 Crystal Instruments Corporation. All Rights Reserved. 08/2023

Notice: This document is for informational purposes only and does not set forth any warranty, expressed or implied, concerning any equipment, equipment feature, or service offered or to be offered by Crystal Instruments. Crystal Instruments reserves the right to make changes to this document at any time, without notice, and assumes no responsibility for its use. This informational document describes features that may not be currently available. Contact a Crystal Instruments sales representative for information on features and product availability.